



ecology and environment, inc.

160 SPEAR STREET, SAN FRANCISCO, CALIFORNIA 94105, TEL. 415/777-2811

International Specialists in the Environment

MEMORANDUM

TO: .	Paul LaCourreye	e, EPA Region I	X		
FROM:	Karen Ladd, Eco	logy and Envir	onment, Inc.		
DATE:	July 23, 1991				
SUBJECT:	Completed Work				
cc:	Marcia Brooks,	E & E FIT			
Attached is	the following con	mpleted:			
PA	PA Review_X	SSI	LSI	SIRe	
Other					
Site Name:	HPM Building	Supply			
EPA ID #: HID981164254 (2890)					
City, County	: Hilo, Hawaii				
State Recommendation: Further Action under CERCLA Recommended (for Reviews only)					
		FOR EPA USE ON	LY		THE TOTAL
CERCLIS Lead		Al	Complet		
		7.3t.	71 "	<u>H"</u>	
		more)	Prl		
n/awni/cwm		3/3/1.			

recycled paper

cn/awpi/cwm

PRELIMINARY ASSESSMENT REVIEW

SUBMITTED TO:

Paul La Courreye, EPA Region IX Site Assessment Manager

PREPARED BY:

Chris Nelson, Ecology and Environment. Inc.

DATE:

July 22, 1991

SITE:

HPM Building Supply, prepared by Philip Moravcik, of

Hawaii State Office of Hazard Evaluation and Emergency

Response, dated May 1991.

TDD#:

F9-9103-020

EPA ID#:

HID981164254

FIT REVIEW/CONCURRENCE: Garet C Kaps 7/24/91

cc: FIT Master File

INTRODUCTION

This Preliminary Assessment has been reviewed by Ecology and Environment, Inc.'s Field Investigation Team (E & E FIT) according to U.S. Environmental Protection Agency (EPA) guidelines presented in the "Preliminary Assessment Interim Guidance Document for Fiscal Year 1988." FIT has evaluated this site with respect to the Hazard Ranking System (HRS) (Federal Register, Vol. 55, No. 421, 51532-51667, December 14, 1990).

RCRA STATUS

x Generator	Small Quantity Generator	Transporter
TSD	Not Listed in RCRA Database	

HRS CONSIDERATIONS

The following are significant HRS factors associated with the HPM site:

An observed release to surface water from an on-site chemical spill has been documented;

cn/awpi/prv

- o Large fisheries are associated with human food chain population;
- o Several federally-designated endangered and threatened species are located within 4 miles of the site; and
- o There is a high potential to document an observed release to groundwater from the site.

COMMENTS

Some general comments about the contents of the report are listed below:

- o Data supporting evidence of actual contamination (if any) following the removal action should be noted;
- o The depth to groundwater and depth to aquifer of concern are not discussed in the report;
- o No figures were included in the report;
- o Data on population within 4 miles of the site was not available to score the air and soil exposure pathways;
- o More detailed information on sensitive environments (e.g. location and type) should be stated in the text in order to properly assess the impacts on these targets while scoring the site;
- o If fish kill data is available to the author, then it should be briefly discussed in the text; and
- o Fish catch data listed in the text of the report is inconsistent with the data presented in the HRS worksheets.

CONCLUSIONS

X Potentially eligible for National Priorities List
Appears to be ineligible for National Priorities List
STATE RECOMMENDATION
No Further Remedial Action Planned under CERCLA
X Further Remedial Action Recommended
Medium-priority Screening Site Inspection (mSSI)
High-priority Screening Site Inspection (hSSI)

EPA RECOMMENDATION

No Further Remedial Action Planned under CERCLA

Higher-Priority SSI under CERCLA

Lower-Priority SSI under CERCLA

Defer to Other Authority
(e.g., RCRA, TSCA, NRC)

Notes: